

## SERVICE BULLETIN


VERSION	00	01/07/05	First version
	01	23/03/06	Updating

Document n°	FRN-SB2005-05-Double-relay programmer-GB
Brand	Smeg
Models involved	All ovens with electronic programmer and TOC
Cause	Reduction of possibile condensation building outside the door.
Description of the modification	The programmer with 1 relay is replaced by a programmer with two relays, so that the tangential/centrifugal cooling system starts immediately. With the former programmer, the tangential/centrifugal cooling fan switches on and off depending on the TOC, whereas with the new programmer, the cooling fan is activated immediately when switching on the oven and the deactivation is controlled by the TOC.
Date of introduction	Starting from 21/02/05
Interchangeability	YES <b>Important for products produced before this modification:</b> the new programmer can be fitted connecting any of the two relays.


**FRONT VIEW**  
**OLD PROGR. Cod. 816290671**  
**NEW PROGR. Cod. 816290857**



**INTERNAL VIEW**  
**OLD PROGR. Cod. 816290671**



**INTERNAL VIEW**  
**NEW PROGR. Cod.816290857**



## SERVICE BULLETIN

### FRONT VIEW

#### **OLD PROGRAMMERS**

Cod. 816290696

Cod. 816290750

#### **NEW PROGRAMMERS**

Cod. 816290858

Cod. 816290891



### INTERNAL VIEW **OLD PROGRAMMERS**

Cod. 816290696


Cod. 816290750



### **INTERNAL VIEW** **NEW PROGRAMMERS**

Cod. 816290858

Cod. 816290891



## SERVICE BULLETIN

### FRONT VIEW

#### **OLD PROGRAMMERS**

Cod. 816290315

Cod. 816290356

#### **NEW PROGRAMMERS**

Cod. 816290063

Cod. 816290870



### INTERNAL VIEW OLD PROGRAMMERS

Cod. 816290315


Cod. 816290356



### INTERNAL VIEW NEW PROGRAMMERS

Cod. 816290063

Cod. 816290870



**SERVICE BULLETIN**

**FRONT VIEW**

**OLD PROGRAMMER**  
Cod. 816290736

**NEW PROGRAMMER**  
Cod. 816290063



**TWO POSSIBLE INTERNAL CONFIGURATIONS**

**OLD PROGRAMMER**  
Cod. 816290736

**TWO POSSIBLE INTERNAL CONFIGURATIONS**

**NEW PROGRAMMER**  
Cod. 816290063

